

Ford Model T Coils - 1913-1927

Connections/ Ohm Readings

A-B: $\infty\Omega$ (w/points open)

A-C: 0Ω

A-E: 0.295Ω (w/points closed)

B-E: 0.295Ω

C-D: 3300Ω


Note: Connections at A and B are sometimes reversed (more common on K-W coils).

Condenser

0.40-0.45 μF

replacement capacitor spec:

0.47 μF , >400VDC, >600V/ μsec (dV/dt rating)



Problem Causes - Symptoms


- **Condenser Open** – heavy blue arc on points but no spark (A-B $\infty\Omega$ w/ points open)
- **Condenser Shorted** – no arc on points, no spark and irregular current draw (A-B 0Ω w/ points open)
- **Secondary Coil Open** – points vibrate and no spark (C-D $\infty\Omega$)
- **Secondary Coil Shorted** - points vibrate but irregular spark (C-D 0Ω)
- **Primary Coil Shorted** – points don't vibrate and irregular current draw (B-E 0Ω)
- **Primary Coil Open** – points don't vibrate, no current draw and points are clean/adjusted (B-E $\infty\Omega$)

Cushion Spring Gap:

(cushion spring touching rivet head with very light pressure, make all four coils the same gap)

0.003-0.005" (Ford)

0.010-0.012" (recommended)



Point Gap:

1/32" or 0.029-0.031"

(with lower bridge pulled down to core)